THOMSON Vicki

From:

GWalker@xstratacopper.com.au

Sent:

Wednesday, 11 April 2012 12:51 PM

To:

Ormonde Katie

Cc:

ccarr@xstratacopper.com.au; bcallaghan@xstratacopper.com.au;

MJohnston@xstratacopper.com.au; DLAUSCopper-EHMCompliance@xstrata.int

Subject: RE: HPI - fall from truck

Hi Katie,

Your points are valid and we did discuss them during the investigation. I will re-visit the investigation but

I would like to include s78B(2) in the review.

s78B(2) - Personal Information

s78B(2) I'll have an amended report to you by next Friday or at least provide some explanation on the points below. EASE ONRIN

Please let me know if this is not acceptable.

Regards

Greg Walker

Underground Manager, Ernest Henry Mining

Xstrata Copper

Telephone: +61 7 4769 4531

Fax: +61 7 47694555

Mobile-Sch4 - Personal Information

Email: gwalker@xstratacopper.com.au

www.xstratacopper.com

From: Ormonde Katie [mailto:Katie.Ormonde@deedi.qld.gov.au]

Sent: Tuesday, April 10, 2012 6:59 AM

To: Walker, Greg (Ernest Henry - Copper)

Subject: RE: HPI - fall from truck

Hi Greg,

I can't seem to get the EHM compliance email address - everything has bounced back.

Just so you know, thanks Katie

From: Ormonde Katie

Sent: Tuesday, 10 April 2012 6:57 AM

To: DLAUSCopper-EHMCompliance@xstrata.int

Cc: 'GWalker@xstratacopper.com.au' Subject: FW: HPI - fall from truck

Hi,

Please see below. I had the wrong email address before.

Regards,

Katie Ormonde

Inspector of Mines

Mines and Energy

Department of Employment, Economic Development and Innovation

RTI- 238

File A

Level 1, 187 Stanley St, Townsville QLD 4810 PO Box 1752, Townsville QLD 4810

t: +61 7 4760 7405 499\$ch4 - Personal Information

f: +61 / 4760 /400

e: katie.ormonde@deedi.gld.gov.au

From: Ormonde Katie

Sent: Tuesday, 10 April 2012 6:54 AM To: 'GWalker@xstratacopper.com.au' Cc: 'ehmcompliance@xstrata.com.au' Subject: RE: HPI - fall from truck

Hi Greg,

I looked at this incident investigation report (Fall from Atlas Copco 6020 Haul Truck)

The investigation report seem to lack detail on the issue of how the truck got to be working on site without the handrail in place. I know there is the first action - Amend SHMS to include requirements for developing controls to manage the risk of working at heights on mobile equipment for activities outside of those that are managed by the on the ground maintenance strategy - pg 8. I understand that this action item can be all encompassing but there does seem to be be more of a focus in the report on everything that the operator failed to do in the causes.

Did EHM pass the truck out without the handrails? (*Previously installed handrails were removed before TR178* was inspected and passed out to be operated by EHM pg. 8) If EHM did pass the truck out, then I can't see any actions that will address this.

If other trucks have the hand rail why didn't this one?

The remedial actions should be specific about reviewing (or developing) a management / approval process of equipment coming to work on site. Is there a need for a Operability and Maintenance Risk assessment on equipment for example? I am not sure that a pre-start check would be the place to pick up on the missing handrail.

And were there any failings from Barminco?

I ask this because there was a similar incident (with Barminco) in September last year at Mount Gordon and Barminco should have known from that incident that there was a need for a handrail on the back of these trucks.

There is no reference to Contractor Management in the report?

And could you consider contacting Atlas Copco about changing the colour of the mud guard?

And I know this is probably just a technicality but could you consider putting - install a handrail on the machine and check any others have hand rails as action items.

Could you please review the investigation report and provide a revised copy.

Regards,

Katie Ormonde

Inspector of Mines

Mines and Energy

Department of Employment, Economic Development and Innovation

Level 1, 187 Stanley St, Townsville QLD 4810

PO Box 1752, Townsville QLD 4810

t: +61 7 4760 7405

149-Sch4 - Personal Information

14/01/2014

f: +61 7 4760 7400

e: katie.ormonde@deedi.gld.gov.au

From: GWalker@xstratacopper.com.au [mailto:GWalker@xstratacopper.com.au]

Sent: Thursday, 5 April 2012 3:00 PM To: Ormonde Katie; Casey Phillip

Cc: MJohnston@xstratacopper.com.au; ccarr@xstratacopper.com.au; bcallaghan@xstratacopper.com.au;

DLAUSCopper-EHMCompliance@xstrata.int

Subject: HPI - fall from truck

Katie and Phil,

Please find attached the investoigation report for the operator that fell from the Atlas Copco 6020 haul truck.

Apologies for this being late.

The hard copy with all appendices is in the mail. Please let me know if you have ELEASE OF

Regards

Greg Walker

Underground Manager, Emest Henry Mining Xstrata Copper

Telephone: +61 7 4769 4531

Fax: +6<u>1 7 47694555</u>

Mobi#9:-Sch4 - Personal Information

Email: qwalker@xstratacopper.com.au

www.xstratacopper.com

The information contained in this e-mail is confidential and is

intended only for use of the addressee

If you receive this e-mail in error, use, distribution, or

copying of this e-mail is not permitted. You are requested to

forward unwanted e-mail and address any problems to the

Xstrata ICT Service Desk.

Xstrata ICT Service Desk e-mail: supportcentre@xstrata.com.au

Xstrata ICT Service Desk phone: Australia 1800 500 646

International +61 2 9034 3710

The information contained in the above e-mail message or messages (which includes any attachments) is confidential and may be legally privileged. It is intended only for the use of the person or entity to which it is addressed. If you are not the addressee any form of disclosure, copying, modification, distribution or any action taken or omitted in reliance on the information is unauthorised. Opinions contained in the message(s) do not necessarily reflect the opinions of the Queensland Government and its authorities. If you received this communication in error, please notify the sender immediately and delete it from your computer system network.

PATION PARISE PA

THOMSON Vicki

From: GWalker@xstratacopper.com.au

Sent: Sunday, 22 April 2012 5:50 PM

To: Ormonde Katie

Cc: bcallaghan@xstratacopper.com.au; ccarr@xstratacopper.com.au;

MJohnston@xstratacopper.com.au

Subject: Re: HPI - fall from truck

Hi Katie,

As discussed on the phone on Friday most of the issues you raised were considered during the investigation process, however we did not consider them to be direct causes of the incident and hence left the incident report containing only the information that was directly related to this incident.

The following information should answer your questions:

1. Focus on operator failures in the report

We have focussed on the operator failures within our report because the incident would not have occurred if the existing EHM controls were adhered to by the operator. In this regard, I particularly note working from heights site procedure, which if adhered to would not have resulted in this incident. Now that we have had this experience we will be changing aspects of the safety management system to include more controls beyond those that are reliant on the operator. This includes requirements for specific consideration to be given to the requirement for handrails when assessing a vehicle's fit for purpose. This will be done through a risk-based check list that provides prompts for a risk assessment.

2. EHM allowing truck on site

The controls at the time of the incident did not include handrails as they are not supplied by Atlas Copco on these units as a standard item and they were not expected to be installed as part of our site requirements. The truck therefore passed our site access inspection procedure as undertaken by the Mobile Maintenance Superintendent.

The investigation did not list this as a causative factor for the incident as the requirement for handrails on these vehicles did not exist at the time of the incident. We have as an action item required handrails to be installed on 6020 trucks going forward before they are allowed site access.

With regard to some trucks on site having handrails and others not, the Barminco equipment arrived from several other sites for the work at EHM. Some of the equipment arrived with handrails installed and some did not. As set out above, our site access systems did not mandate handrails at that stage and so this was not considered an issue at the time.

3. Updated site access procedure

As set out above, our site access procedures have been updated to require specific consideration of handrails all mobile equipment going forward before they are allowed site access. Pre start checks of the handrails will be another control layer in the system to ensure that the handrails remain functional.

4. Barminco and Mount Gordon incident

At the time of the incident, we were not aware that not having handrails on these items of equipment had been an issue at any other sites.

As stated above, the focus of our report has been on the failings to adhere to the existing EHM controls

rather than investigating incidents on other sites.

5. Contract management

We are not aware of any contractor management failings. Again, our view is that if the EHM site controls had been adhered to then the incident would not have occurred.

Mud guard colour - Atlas Copco discussion

We will contact Atlas Copco about the colour of the mudguard.

7. Request to update action items regarding handrail installation and check of other equipment

I think this is addressed as an action item in the report already but happy to discuss if you believe that this can be expressed more clearly. SE ONRM

Regards

Greg Walker Underground Manager, Ernest Henry Mining Xstrata Copper

Telephone: +61 7 4769 4531 Fax: +61 7 47694555 Mobile Sch4 - Personal Information

Email: gwalker@xstratacopper.com.au www.xstratacopper.com

From: Ormonde Katie [mailto:Katie.Ormonde@deedi.gld.gov.au]

Sent: Tuesday, April 10, 2012 6:54 AM To: Walker, Greg (Ernest Henry - Copper) Cc: 'ehmcompliance@xstrata.com.au'

Subject: RE: HPI - fall from truck

Hi Greg.

I looked at this incident investigation report (Fall from Atlas Copco 6020 Haul Truck).

The investigation report seem to lack detail on the issue of how the truck got to be working on site without the handrail in place. I know there is the first action - Amend SHMS to include requirements for developing controls to manage the risk of working at heights on mobile equipment for activities outside of those that are managed by the on the ground maintenance strategy - pg 8. I understand that this action item can be all encompassing but there does seem to be be more of a focus in the report on everything that the operator failed to do in the causes.

Did EHM pass the truck out without the handrails? (Previously installed handrails were removed before TR178 was inspected and passed out to be operated by EHM pg. 6) If EHM did pass the truck out, then I can't see any actions that will address this.

If other trucks have the hand rail why didn't this one?

The remedial actions should be specific about reviewing (or developing) a management / approval process of equipment coming to work on site. Is there a need for a Operability and Maintenance Risk assessment on equipment for example? I am not sure that a pre-start check would be the place to pick up on the missing handrail.

And were there any failings from Barminco?

File A 6 of 17 RTI- 238

I ask this because there was a similar incident (with Barminco) in September last year at Mount Gordon and Barminco should have known from that incident that there was a need for a handrail on the back of these trucks.

There is no reference to Contractor Management in the report?

And could you consider contacting Atlas Copco about changing the colour of the mud guard?

And I know this is probably just a technicality but could you consider putting - install a handrail on the machine and check any others have hand rails as action items.

Could you please review the investigation report and provide a revised copy.

Regards,

Katie Ormonde

Inspector of Mines

Mines and Energy

Department of Employment, Economic Development and Innovation

Level 1, 187 Stanley St, Townsville QLD 4810

PO Box 1752, Townsville QLD 4810

t: +61 7 4760 7405

4975ch4 - Personal Information

f: +61 7 4760 7400

e: katie.ormonde@deedi.gld.gov.au

From: GWalker@xstratacopper.com.au [mailto:GWalker@xstratacopper.com.au]

Sent: Thursday, 5 April 2012 3:00 PM **To:** Ormonde Katie; Casey Phillip

Cc: MJohnston@xstratacopper.com.au; ccarr@xstratacopper.com.au; bcallaghan@xstratacopper.com.au;

DLAUSCopper-EHMCompliance@xstrata.int

Subject: HPI - fall from truck

Katie and Phil,

Please find attached the investoigation report for the operator that fell from the Atlas Copco 6020 haul truck.

Apologies for this being late.

The hard copy with all appendices is in the mail. Please let me know if you have any questions.

Regards

Greg Walker

Underground Manager, Emest Henry Mining

Xstrata Copper

Telephone: +61 7 4769 4531

Fax: +61 7 47694555

Mobile: Sch4 - Personal Information

Email: gwalker@xstratacopper.com.au

www.xstratacopper.com

The information contained in this e-mail is confidential and is intended only for use of the addressee(s). If you receive this e-mail in error, any use, distribution, or copying of this e-mail is not permitted. You are requested to forward unwanted e-mail and address any problems to the Xstrata ICT Service Desk.

Xstrata ICT Service Desk e-mail: supportcentre@xstrata.com.au
Xstrata ICT Service Desk phone: Australia 1800 500 646
International +61 2 9034 3710

The information contained in the above e-mail message or messages (which includes any attachments) is confidential and may be legally privileged. It is intended only for the use of the person or entity to which it is addressed. If you are not the addressee any form of disclosure, copying, modification, distribution or any action taken PATION PER PARAMENTAL PROPERTY OF THE PARAMETER PROPERTY OF THE PARAMETER PA or omitted in reliance on the information is unauthorised. Opinions contained in the message(s) do not necessarily reflect the opinions of the Queensland Government and its authorities. If you received this communication in error, please notify the sender immediately and delete it from your computer system network.

R

From:

phillip.casey@deedi.qld.gov.au

Sent:

Thursday, 9 February 2012 7:01 AM

To:

Ormonde Katie; Lee Damian; Perkins Roy; Sur Asok; Thomson Vicki; Casey Phillip; Fasching

Hermann; Cespedes Sergio

Subject: New Form 1A #PCAY-8RASGQ

The following is a transcript of the Form 1A Notification:

Part 1: Details Of Notifier And Receiver

Name of Mine/Quarry: Ernest Henry - Underground Name of Owner / Operator: Ernest Henry Mining Pty Ltd

Mine Type: Metalliferous Mine File No: 20015 / 01

Caller's Na788(2) - Personal Information

Caller's Contact Number:

Caller's Position / Title: Underground Manager Notification Received: 6:15:00 PM, 8/02/2012

Receiver Name: Phillip Casey Receiver Contact Details:

Part 2: Details Of The Event

Time: 3:00:00 PM Date: 8/02/2012

Location (section / area): Bench outside portal entrance

Equipment Involved: 60 tonne underground truck

Environmental conditions: Light

E. ONRIN General Description: Operator standing on the engine compartment of a truck slipped and fell

approximately 2.3 metres to the ground. It appears a rubber flap may have appeared solid and gave way

underneath him when he stood on it.

PERSONS INVOLVED

NAME Section 78B(2) RTI Act

INJURIES: s78B(2) - Personal Information
EMPLOYEE/CONTRACTOR/GENERAL PUBLIC: Contractor (Barminco) CURRENT STATUS: Being flown by rescue helicopter to \$78B(2) Hospital

NAME:

INJURIES:

EMPLOYEE/CONTRAC OR/GENERAL PUBLIC:

CURRENT STATUS:

NAME:

INJURIES:

EMPLOYEE/CONTRACTOR/GENERAL PUBLIC:

CURRENT STATUS:

NAME:

INJURIES:

EMPLOYEE/CONTRACTOR/GENERAL PUBLIC:

CURRENT STATUS:

Other Details:

Part 3: Mobilisation Of Emergency Services And Other Initial Actions

Are Emergency Services Required? YES

Have Emergency Services Been Notified? YES

Have Police Been Notified? NO

Are SIMTARS Services Required / No NO

Are Other DNR&M Inspectorate Branches Required / Been Informed? Explosives Branch Required? NO Informed? Gas & Petroleum Branch Required? NO Informed?

Has The Site Been Made Safe? YES Explanatory comment (if any): Is The Site Effectively Isolated To Preserve Evidence? YES Explanatory comment (if any): Other Actions Taken By Mine / Quarry (if any):

Instruction To Be Given To Mine / Quarry eg SUBMIT BASIC DETAILS BY FAX ASAP: Other Instruction Or Advice Given (if any):

Part 4: Communication To The Inspectorate

NATURE OF THE EVENT: Emergency Coal Mine Disaster or Multiple Fatalities ACTIONS REQUIRED: REFER EMERGENCY PROCEDURES MANUALS, Coal Emergency Duty Officer Ph: 3237 1696

73(2)Irrelevant

She oper Shoken back Said to sen

35

73(2)Irrelevant

From:

Jade Bartlett [jbartlett@xstratacopper.com.au]

Sent:

Friday, 6 April 2012 9:46 AM

To:

MIR-Administration; MIR-MtIsa

Cc:

jbartlett@xstratacopper.com.au

Type of incident

Subject: Completed Mining incident report No. 121690 (High potential lost time)

Incident report number: 121690

Recipients: jbartlett@xstratacopper.com.au and miradministration@deedi.qld.gov.au

Incident type: High potential lost time

2 Summary/title of incident

> A Truck driver was parked up at the bench in the Atlas Truck 178 waiting for the trainer and assessor to come down and assess him. Whilst waiting the Operator decided to clean the back window. As he commenced to clean the back window he stood back on the mud guard, which looked similar and it is likely that the driver stood on the mud guard and it gave way causing him to lose his footing falling approximately 2.3 metres back onto the ground on to his right hip.

> > ELEASE

112 - Persons-falling

Code: M00199

Old Code:

ERNH

Code: 191 - Haul road-portal area

Previously notified: Yes

Date: 08/02/2012

Mine details

Mine/quarry name Ernest Henry - Mine

5 Mine type: MetalliferousSurface

Company contact: Jade Bartlett

Phone: 0747694636

Where in the mine did the incident occur? Portal Bench

Surface or underground? surface

Incident details

Date of incident: 08/02/2012

Time of incident: 15 00 (24 hr clock)

10 Time shift started: 06 00

Shift duration: 12 00

No. of complete shifts/day worked prior to accident: 7

No. of days in shift cycle: 21

No. of days rostered off prior to starting current shift cycle: 7

Tot hrs worked in 24 hr period prior to accident, inc travel time: 9

Date of first full working day lost: 08/02/2012

12 Primary equipment/tool involved in incident: Atlas Truck 178

Code: 019 - Load haul dumpunderground

13 Describe exactly how did the incident occur:

R

A Truck driver was parked up at the bench in the Atlas Truck 178 waiting for the trainer and assessor to come down and assess him. Whilst waiting the Operator decided to clean the back window. As he commenced to clean the back window he stood back on the mud guard, which looked similar and it is likely that the driver stood on the mud guard and it gave way causing him to lose his footing falling approximately 2.3 metres back onto the ground on to his right hip.

14 What hazards have been identified from this incident:

No handrail preventing personal falling from heights The mud guard was a similar colour to the structure of the truck

Code: 136 - Working at heights

Unspecified/other

Injured person details

- 15 Sus78B(2)e:Personal Information
- 15 Date of bitil(2) Personal Information
- 17 First name and initial Personal Information
- 18 GABOPT Personal Information
- 19 Employee number: 75648
- 20 Work activity at time of incident: UG Contractor Barminco
- 21 Type of employee: Contractor

if contractor, company name: Barminco

22 Nature of injury/disease: s78B(2) - Personal Information

Body location code:_{s78B(2)} - Personal Information

23 Description of personal damage:

s78B(2) - Personal Information

Is this a permanent incapacity ersonal Information

Incident causes

24 What happened leading up to the injury/incident/disease?

Organisational

Operator failed to identify that was working outside of the site policy for height safety Operator failed to put adequate controls in place to mitigate against the risks of working at height (eg wearing fall protection) Operator was completing a familiarisation prestart before his practical assessment without correct supervision Operator did not complete a Pre Task Risk Assessment (SWIC) prior to completing activity

Codes 106 - Incompatible goals

Task/environment conditions

Codes 304 - Equipment design/construction

Location of guard above wheel arch on Atlas Copco MT6020 is 2.3m above the ground

Individual/team actions

Codes 221 - Other ind./team factor

Operator failed to identify that was working outside of the site policy for height safety Operator failed to put adequate controls in place to mitigate against the risks of working at height (eg wearing fall

13 of 17

protection) Operator was completing a familiarisation prestart before his practical assessment without correct supervision Operator did not complete a Pre Task Risk Assessment (SWIC) prior to completing activity

Absent or failed defenses

The EHM Safety and Health Management System strategy is to maintain and service mobile equipment from the ground level. Rubber guard not designed to support weight of operator Rubber guard difficult to distinguish between metal and rubber surface Operator in training to operate Atlas Trucks Previously installed handrails were removed before TR178 was inspected and passed out to be operated at EHM

Codes

420 - Absent/failed defence factor (not specified)

Preventative action

25 Give details of any control measures/actions being considered and/or implemented to prevent reoccerences

Amend site Safety and Health Management System to include requirements for developing controls to manage the risk of working at heights on mobile equipment for activities outside of those that are managed by the on the ground maintenance strategy. Performance management of operator in the areas of: 1. Requirement for working at heights (operator had WAH training competency) 2. Completion of pre task risk assessment 3. Operation of equipment without correct training Inspect all underground mobile equipment to ensure all handrails and edge protection is fitted and serviceable Amend Barminco heavy vehicle pre-start checklists to include requirement to check that fall protection controls (eg handrails) are in place Intermediate (Implementation 3 â€* 6 months) Develop Xstrata EHM underground heavy vehicle pre-start checklists for each type of vehicle operating underground. Include a check of serviceable fall protection controls (eg handrails) on checklists. Include in the assessment the practicality of the controls Long Term (Implementation 6+ months) Audit the above actions after 15 September 2012 to ensure that requirements put in place after February HPI are still in place

Date: 06/04/2012	
Your full name: Jade Bartlett	
Position: SD Administration Assistant	
Email: jbartlett@xstratacopper.com.au	
Office use	
86103	7010179
Inspector/inspection officer: Signed: Entered by:	A9-Sch4 - Personal Information

From: Jade Bartlett [jbartlett@xstratacopper.com.au]

Sent: Friday, 2 March 2012 2:19 PM

To: MIR-Administration; MIR-MtIsa Cc: jbartlett@xstratacopper.com.au

Subject: Mining Incident Monthly Summary Report - 011924 - Completed

Monthly incident summary report.

Submission details


Receipt number: 011924


For the period: Feb 2012 Submitted by: Jade Bartlett

Mine name: Ernest Henry - Mine

 Mine code: M00199 Old Mine code: ERNH

 Hours worked this period by employees: 96140 Hours worked this period by contractors: 91379





No medical treatments for this period.

No carried over lost time injuries for this period.

No new disabling injuries for this period.

No carried over disabling injuries for this period.

No re-opening claims for this period.

Note: Incident summary form numbers must be 5 digits.

Note 1 List all medical treatments during the period.

Note 2 List all new cases of company employees and contractors off during the period.

Note 3 List carry over incidents from the previous period.

Note 4 List all re-opened claims. List original form number.

User IP address: 10.6.64.33

User agent: Mozilla/4.0 (compatible; MSIE 6.0; Windows NT 5.1; SV1; .NET CLR 1.1.4322; .NET CLR 2.0.50727; .NET CLR 3.0.4506.2152; .NET CLR 3.5.30729; .NET4.0C; .NET4.0E; InfoPath.2)

Email address: jbartlett@xstratacopper.com.au

Jade Bartlett [jbartlett@xstratacopper.com.au] From:

Sent: Wednesday, 4 April 2012 9:49 AM To: MIR-Administration; MIR-Mtlsa Cc:

jbartlett@xstratacopper.com.au

Subject: Mining Incident Monthly Summary Report - 012103 - Completed

Monthly incident summary report.

Submission details

Receipt number: 012103

 For the period: Mar 2012 Submitted by: Jade Bartlett

Mine name: Ernest Henry - Mine

 Mine code: M00199 Old Mine code: ERNH

 Hours worked this period by employees: 101729 Hours worked this period by contractors: 153893

Carry over lost time injuries from previous period/s. List original incident form number (see note 3)

No.	Incident form No.	Surname	First name	Brief description of personal damage	first full working	No. of Working days lost this period	period on alt.	work?	Incapacity type	Workcov Ref No.
1	130244				s78B(2) - Per					

- No medical treatments for this period.
- No new lost time injuries for this period.
- No new disabling injuries for this period.
- No carried over disabling injuries for this period.
- No re-opening claims for this period.

Note: Incident summary form numbers must be 5 digits.

Note 1 List all medical treatments during the period.

Note 2 List all new cases of company employees and contractors off during the period.

Note 3 List carry over incidents from the previous period.

Note 4 List all re-opened claims. List original form number.

User IP address: 10.6.64.33

User agent: Mozilla/4.0 (compatible; MSIE 8.0; Windows NT 5.1; Trident/4.0; .NET CLR

From:

Jade Bartlett [jadeolivia@windowslive.com]

Sent:

Wednesday, 2 May 2012 11:01 AM

To:

MIR-Administration; MIR-Mtlsa

Cc:

jadeolivia@windowslive.com

Subject: Mining Incident Monthly Summary Report - 012287 - Completed

Monthly incident summary report.

Submission details

Receipt number: 012287

For the period: Apr 2012

Submitted by: Jade Bartlett

Mine name: Ernest Henry - Mine

Mine code: M00199

Old Mine code: ERNH

Hours worked this period by employees: 103638

Hours worked this period by contractors: 123487

JAP 4 C.L S

Medical treatments for this period (see note 1)

No. Surname	First name	Brief description of personal damage	
1		Section 786(2) RTI Act	

Carry over lost time injuries from previous period/s. List original incident form number (see note

No.	Incident form No.	Surname	First name	Brief description of personal damage	Working	No. of working days lost this period	period	work?	Incapacity type	Workcov Ref No.
1	129961				Section 78	3B(2) RTI Ac				

- No new lost time injuries for this period.
- No new disabling injuries for this period.
- No carried over disabling injuries for this period.
- No re-opening claims for this period.

Note: Incident summary form numbers must be 5 digits.

Note 1 List all medical treatments during the period.

Note 2 List all new cases of company employees and contractors off during the period.

Note 3 List carry over incidents from the previous period.

Note 4 List all re-opened claims. List original form number.